



6,845,333.

02.18-05

PATENT  
CASE NO. 1444-0014.01

CofC

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Group:	2857	) <u>Certificate Under 37 C.F.R. 1.8(a)</u>
Confirmation No.:	8972	) I HEREBY CERTIFY THAT THIS CORRESPONDENCE IS BEING
Application Serial No.:	10/729,135	) DEPOSITED WITH THE UNITED STATES POSTAL SERVICE AS
Title: PROTECTIVE RELAY WITH		) EXPRESS MAIL IN AN ENVELOPE ADDRESSED TO
SYNCHRONIZED PHASOR		) COMMISSIONER FOR PATENTS, P.O. Box 1450,
MEASUREMENT CAPABILITY FOR USE		) ALEXANDRIA, VIRGINIA 22313-1450
IN ELECTRIC POWER SYSTEMS		) ON <u>2/16/15</u>
		) (DATE OF DEPOSIT)
		)
		)
		)
		)
Applicant:	Schweitzer Engineering Laboratories, Inc.	) _____ DAVID M. MUMDT
Filed:	12-05-2003	) NAME OF APPLICANT, ASSIGNEE, OR REGISTERED REP.
Examiner:	RAYMOND, EDWARD	)  2/16/15
		) SIGNATURE DATE

## **Request For Certificate of Correction**

To: Mail Stop Post Issue  
Attention: Certificate of Correction Branch  
Commissioner for Patents  
P.O. Box 1450  
Alexandria, Virginia 22313-1450

**Certificate**  
**FEB 24 2005**

## of Correction

Sir:

Upon review of the above-identified U.S. Patent No. 6,845,333, issued January 18, 2005, a number of errors were noted. The enclosed Certificate of Correction illustrates these errors.

Respectfully submitted,

Cook, Alex, McFarron, Manzo, Cummings & Mehler, Ltd.

By:

David M. Mundt, Registration No. 41,207

200 West Adams, Suite 2850  
Chicago, Illinois 60606

(312) 984-0144

February 16, 2005

UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION

PATENT NO. : 6,845,333

DATED : January 18, 2005

INVENTOR(S) : Edmund O. Schweitzer, III, et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

"Edmund O. Schweitzer, III" should be listed as the first inventor;

The second inventor's name is misspelled and should be listed as "Luther S. Anderson";

The last inventor's name is misspelled and address is incomplete, and should be listed as "Gabriel Benmouyal, Boucherville, Quebec, CANADA"

MAILING ADDRESS OF SENDER:

Cook, Alex, McFarron, Manzo, Cummings & Mehler, Ltd.  
200 West Adams Street, Suite 2850  
Chicago, Illinois 60606

PATENT NO. 6,845,333

No. of additional copies

MAP 7 2005



This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

*If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.*